PILOT'S OPERATING HANDBOOK

and

AIRPLANE FLIGHT MANUAL for the



Mfgr's Serial	No.	·
Registration	No.	

This aircraft is FAA Approved in the EXPERIMENTAL category based on FAR 23. This document may be carried in the aircraft at all times.

Owners are encouraged to evaluate their own check-lists and owner developed manual data for completeness based on this handbook.

Published by

Lancair International Inc.

Redmond, Oregon 97756

Authorized Dealer

Neico Aviation Inc. 2244 Airport Way Redmond, Oregon 97756

PILOT'S OPERATING HANDBOOK and AIRPLANE FLIGHT MANUAL

December, 1994

Log of Revisions

PAGES	DESCRIPTION		
	9		
	La la companya de la		

INTRODUCTION

This Lancair International Pilot's Operating Handbook and Airplane Flight Manual is in the format and contains most data recommended in the GAMA (General Aviation Manufacturers Association) Handbook Specification Number 1. Use of this specification provides the pilot the same type data in the same place in all of the handbooks.

For example, attention is called to Section X, SAFETY INFORMA-TION. We feel it is very important to have this information in a condensed and readily available location and format for the pilots immediate use when needed.

This SAFETY INFORMATION should be read and studied by all operators of the Lancair 235, 320 and 360 aircraft and will provide a periodic review of good piloting techniques for this aircraft. This manual will not replace safe flight instruction or good piloting techniques.

NOTE:

Owner modifications to your Lancair may alter the applicability of this handbook which meets the GAMA specification #1 for pilots operating handbooks.

WARNING

Use only genuine Lancair approved parts obtained from authorized Lancair dealers when repairing your Lancair 235/320/360.

Lancair parts are produced and inspected under controlled procedures to ensure airworthiness commensurate with use in the Lancair. Other than these approved parts, while appearing suitable, may not have been fabricated under adequately controlled conditions and may be unsuitable and dangerous when used in your Lancair.